



Vehicle Condition Inspection

Date: 02/19/2015

ASSIGNMENT INFORMATION

Date of Inspection	02/19/2015
Purpose of Inspection	Actual Cash Value
Main Vehicle Picture	
Name of Inspector	

VEHICLE INFORMATION

VIN	2G1WL15C669396579
Year	2006
Make	CHEVY
Model	MONTE CARLO
Trim	SS
Mileage	83928
Mileage Category	Actual
Cylinders	8
Engine	Gas
Transmission	Automatic Shift
Drivetrain	2WD
Options	Leather Sunroof Premium Wheels

Other Options

Upgraded brakes and exhaust, custom racing stripes, hood scoop, spoiler numbered car.



VEHICLE CONDITION

Item	Seats
Condition Grade	4- Good
Item	Carpet
Condition Grade	4- Good
Item	Headliner
Condition Grade	4- Good
Item	Doors
Condition Grade	4- Good
Item	Interior Panels
Condition Grade	4- Good
Item	Dash / Console
Condition Grade	4- Good
Item	Glass / Windows
Condition Grade	4- Good
Item	Body
Condition Grade	4- Good
Item	Paint
Condition Grade	3- Average
Item	Engine
Condition Grade	4- Good
Item	Transmission
Condition Grade	4- Good
Item	Tires
Condition Grade	5- Excellent

PHOTOS

Item	Engine Bay
------	------------

Vehicle Condition Inspection

Date: 02/19/2015

Image




Image Notes

5.3 V8


Item

VIN Sticker

Vehicle Condition Inspection

Date: 02/19/2015

Image



Item

Odometer

Vehicle Condition Inspection

Date: 02/19/2015

Image



Image Notes

83,928

Item

Other

Vehicle Condition Inspection

Date: 02/19/2015

Image



Image Notes

interior

Item

Rear (must show tag)

Image




Image Notes

NK3144

Item

Registration Card

Vehicle Condition Inspection

Date: 02/19/2015

Image



Item

Front

Vehicle Condition Inspection

Date: 02/19/2015

Image



Item

Front and Left Side

Vehicle Condition Inspection

Date: 02/19/2015

Image



Item

Left Side and Rear

Vehicle Condition Inspection

Date: 02/19/2015

Image



Item

Rear and Right Side

Vehicle Condition Inspection

Date: 02/19/2015

Image



Item

Right Side and Front

Vehicle Condition Inspection

Date: 02/19/2015

Image



INSPECTION NOTES

General Notes

GREAT SOUNDING EXHAUST.